



Release Notes for FAB10Gxxx
Release 8.28-20 dated 7-19-2016:

Features Added:

- 1) New GUI for configuration maps, filters, and Traffic Rate Statistics pages

Known Limitations:

- 1) Users must set port speed to auto when:
 - a. Swapping SFP/SFP+ modules on that port.
 - b. Changing port force-speed on that port.

Resolved Issues:

- 1) SNMP Read shows information for specific Vendor
- 2) Unexpected filters created if the save button is activated before update/add process done

Image Upgrade:

Users may upgrade using the web UI's "Firmware Upgrade" page or from the CLI with the following command:

```
archive download-sw /overwrite tftp://<TFTP server IP>/vmlinux.64.gz
```

For **all** devices, a power cycle is required after the firmware upgrade has completed.

For questions, please contact Garland Technical Support at:

8 AM – 9 PM (CST) Monday – Friday (except for observed US Holidays)
+1.716.242.8500 support@garlandtechnology.com